


Repair kit magnetic coupling ALP-0100 – 0115

Note The repair kit contains only the numbered parts and is only supplied complete.



Qty.	Pos. No.	Part	Qty.	Pos. No.	Part
1	053	Coupling hub	1	739.2	O-ring
1	515	Outer rotor	1	884	Threaded pin
1	518	Inner rotor	4	914.5	Socket screw

Tab. 1: Repair kit magnetic coupling ALP-0100 – 0115